


# NYMAX™ BIO

## BIO-BASED POLYAMIDE SOLUTIONS



Formulated in glass fiber-filled or unfilled materials, **Nymax™ BIO** formulations utilize between 16 and 47 percent natural filler from renewable plant-based raw materials, reducing the carbon footprint value significantly at the beginning of the product lifecycle. These highly engineered formulations deliver comparable performance to traditional PA66 glass fiber-

filled materials, plus the bio-derived solutions offer lower warpage and have excellent surface appearance and colorability. Nymax BIO low water absorption PA formulations provide excellent dimensional stability and property retention after conditioning, solving the problem of water uptake (hygroscoy) for finished parts.

Parameters	NM5600-8002 RS	NM5600-8004 RS
<b>Drying Temperature</b>	100–120°C	100–130°C
<b>Drying Time</b>	4–6 hours	4–6 hours
<b>Barrel Temperature</b>	°C	°C
Rear Zone	250–270	260–270
Central Zone	260–280	270–290
Front Zone	270–295	290–305
Nozzle	290–300	290–300
<b>Mold Temperature</b>	80–100	80–100
<b>Screw Speed</b>	Moderate	Moderate
<b>Back Pressure</b>	3–10bar	3–10bar
<b>Cushion stroke</b>	5–10% of plasticizing stroke	5–10% plasticizing of stroke
<b>Injection Speed</b>	Medium	Medium
<b>Injection Pressure</b>	Medium–high	Medium–high
<b>Holding Pressure</b>	30–50% of injection pressure	20–40% of injection pressure
<b>Screw Type</b>	General purpose	General purpose
<b>Screw L/D</b>	20:1	20:1
<b>Screw Compression Ratio</b>	2.5:1	2.5:1
<b>Non-return Check Valve</b>	Free flow check ring	Free flow check ring
<b>Nozzle Type</b>	Reverse taper	Reverse taper
<b>Barrel Capacity</b>	30–80% of barrel should be used	



Start Up & Shut Down	Recommendations
<b>Purge Compound</b>	1. 2–3 melt flow PP or purging compound. PC or PA also recommended
<b>Regrind</b>	1. Regrind is not suggested—glass fiber reinforce material will lose strength after regrind
Mold Design	Recommendations
<b>Gates</b>	<ol style="list-style-type: none"> <li>1. All types of gates can be used such as pin, fan, tunnel, tab and edge gates. Gate type should be select based on location and part geometry.</li> <li>2. Gate diameters should be equivalent to 50-80% of the average wall thickness of the part to be inject.</li> <li>3. A land length of 0.040” (1.0mm) is recommend</li> </ol>
<b>Runners</b>	<ol style="list-style-type: none"> <li>1. Full-round or modified trapezoid runners are the best design and provide the least surface-to-cross-section ratio. Half-round or standard trapezoid runners are not recommended.</li> <li>2. Only naturally balanced runner systems (“H” pattern) are recommended.</li> <li>3. Each 90° bend in the system should step down in size.</li> <li>4. Vents should be placed at the intersection of each 90° bend off of the cold slug well and vented to the atmosphere.</li> <li>5. Hot runner molds are acceptable and should be sized by the manufacturer. Externally heated manifolds are recommended</li> </ol>
<b>Cold slug wells</b>	<ol style="list-style-type: none"> <li>1. Place cold slug wells at the base of the sprue to capture the cold material first emerging from the nozzle.</li> <li>2. Place cold slug wells at every 90° bend in the runner system.</li> <li>3. Well depths approximately 2-3 times the diameter of the runner provide the best results.</li> </ol>
<b>Vents</b>	<ol style="list-style-type: none"> <li>1. Place vents at the end of fill and anywhere potential knit/weld lines will occur.</li> <li>2. All vents need to be vented to the atmosphere.</li> <li>3. Vents should be placed at the intersection of each 90° bend in the runner system off of the cold slug well and vented to atmosphere.</li> </ol>
<b>Draft</b>	1. Draft angle should be 1/2° to 1° per side. Additional draft may be required for grained/textured surfaces.

## TROUBLESHOOTING

Implement recommended solutions one at a time in the order specified until problem is resolved.

Problem	Cause	Solution
<b>Incomplete fill</b>	Melt and/or mold too cold	<ol style="list-style-type: none"> <li>1. Increase nozzle and barrel temperatures</li> <li>2. Increase mold temperature</li> <li>3. Increase injection rate</li> <li>4. Check thermocouples and heater bands</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Enlarge or widen vents and increase number of vents</li> <li>2. Check that vents are unplugged</li> <li>3. Check that gates are unplugged</li> <li>4. Enlarge gates and/or runners</li> <li>5. Perform short shots to determine fill pattern and verify proper vent location</li> <li>6. Increase wall thickness to move gas trap to parting line</li> </ol>
	Shot size	<ol style="list-style-type: none"> <li>1. Increase shot size</li> <li>2. Adjust transfer position to 98% full</li> <li>3. Increase cushion</li> </ol>
<b>Brittleness</b>	Degraded/overheated material	<ol style="list-style-type: none"> <li>1. Decrease melt temperature</li> <li>2. Decrease back pressure</li> <li>3. Use smaller barrel</li> <li>4. Decrease injection speed</li> </ol>
	Gate location and/or size	<ol style="list-style-type: none"> <li>1. Relocate gate to non-stress area</li> <li>2. Increase gate size to allow higher flow rate and lower molded in stress</li> </ol>
	Wet material	<ol style="list-style-type: none"> <li>1. Check moisture of material to ensure it is within the recommended moisture percentage for molding</li> </ol>
<b>Splay</b>	Melt temperature too low	<ol style="list-style-type: none"> <li>1. Increase melt temperature</li> <li>2. Increase mold temperature</li> <li>3. Increase injection speed</li> </ol>
	Wet material	<ol style="list-style-type: none"> <li>1. Check moisture of material to ensure it is within the recommended moisture percentage for molding</li> </ol>
<b>Sink marks</b>	Part geometry too thick	<ol style="list-style-type: none"> <li>1. Reduce wall thickness</li> <li>2. Reduce rib thickness</li> </ol>
	Melt too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures</li> <li>2. Decrease mold temperature</li> </ol>
	Insufficient material volume	<ol style="list-style-type: none"> <li>1. Increase shot size</li> <li>2. Increase injection rate</li> <li>3. Increase packing pressure</li> <li>4. Increase gate size</li> </ol>
<b>Shrink</b>	Too much shrink	<ol style="list-style-type: none"> <li>1. Increase cooling time</li> <li>2. Decrease mold temperature</li> </ol>
	Too little shrink	<ol style="list-style-type: none"> <li>1. Decrease cooling time</li> <li>2. Increase mold temperature</li> </ol>

Problem	Cause	Solution
<b>Flash</b>	Injection pressure too high	<ol style="list-style-type: none"> <li>1. Decrease injection pressure</li> <li>2. Increase clamp pressure</li> <li>3. Decrease injection speed</li> <li>4. Increase transfer position</li> </ol>
	Excess material volume	<ol style="list-style-type: none"> <li>1. Adjust transfer position</li> <li>2. Decrease pack pressure</li> <li>3. Decrease shot size</li> <li>4. Decrease injection speed</li> </ol>
	Melt and/or mold too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures</li> <li>2. Decrease mold temperatures</li> </ol>
	Loose clamp	<ol style="list-style-type: none"> <li>1. Reset mold height</li> <li>2. Increase clamp tonnage</li> </ol>
<b>Burning</b>	Melt and/or mold too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures</li> <li>2. Decrease mold temperature</li> <li>3. Decrease injection speed</li> <li>4. Reduce decompression</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Clean, widen and increase number of vents</li> <li>2. Increase gate size to reduce shear</li> </ol>
	Wet material	<ol style="list-style-type: none"> <li>1. Verify material is dried at proper condition</li> </ol>
<b>Nozzle drool</b>	Nozzle temperature too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle temperature</li> <li>2. Decrease back pressure</li> <li>3. Increase screw decompression</li> <li>4. Verify material has been dried at proper conditions</li> </ol>
	Incorrect nozzle	<ol style="list-style-type: none"> <li>1. Use reverse taper nozzle</li> </ol>
<b>Weld lines</b>	Melt front temperatures are too low	<ol style="list-style-type: none"> <li>1. Increase pack and hold pressure</li> <li>2. Increase melt temperature</li> <li>3. Increase vent width and locations</li> <li>4. Increase injection speed</li> <li>5. Increase mold temperature</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Increase gate size</li> <li>2. Identify end of fill pattern and verify proper vent location</li> <li>3. Add vents or increase vent width</li> <li>4. Move gate location</li> </ol>
<b>Warp</b>	Melt front temperatures are too low	<ol style="list-style-type: none"> <li>1. Increase melt temp</li> <li>2. Reduce injection speed</li> <li>3. Increase pack pressure</li> <li>4. Increase pack time</li> <li>5. Decrease mold temperature</li> <li>6. Increase cool time</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Non-uniform mold cooling</li> </ol>
	Part design	<ol style="list-style-type: none"> <li>1. Non-uniform wall thickness</li> </ol>
	Thermolator incorrect temperature	<ol style="list-style-type: none"> <li>1. Check settings</li> <li>2. Inspect thermocouple</li> </ol>

Problem	Cause	Solution
<b>Sticking in mold</b>	Cavities are over packed	<ol style="list-style-type: none"> <li>1. Decrease injection speed and pressure</li> <li>2. Decrease hold pressure</li> <li>3. Adjust transfer position</li> <li>4. Decrease nozzle and barrel temperatures</li> <li>5. Decrease mold temperature</li> <li>6. Increase cooling time</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Increase draft angle</li> <li>2. Polish cores in direction of ejection</li> </ol>
	Part is too hot	<ol style="list-style-type: none"> <li>1. Decrease barrel temperatures</li> <li>2. Decrease mold temperature</li> <li>3. Increase cooling time</li> </ol>
<b>Black specks</b>	Contamination	<ol style="list-style-type: none"> <li>1. Purge machine</li> </ol>
	Degradation	<ol style="list-style-type: none"> <li>1. Reduce melt temperature</li> <li>2. Reduce screw speed</li> <li>3. Reduce back pressure</li> </ol>
	Machine related	<ol style="list-style-type: none"> <li>1. Check for wear on screw, barrel or check ring</li> </ol>
<b>Delamination</b>	Process related	<ol style="list-style-type: none"> <li>1. Increase melt temperature</li> <li>2. Decrease injection speed</li> <li>3. Purge barrel to eliminate material contamination</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Reduce sharp corners in material flow path</li> <li>2. Increase venting</li> </ol>
<b>Discoloration</b>	Oversheared material	<ol style="list-style-type: none"> <li>1. Decrease melt temperature</li> <li>2. Decrease injection speed</li> <li>3. Reduce residence time</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Increase gate sizing</li> </ol>
	Dry material	<ol style="list-style-type: none"> <li>1. Check moisture of material to ensure it is within the recommended moisture percentage for molding</li> </ol>

1.844.4AVIENT  
www.avient.com



Copyright © 2022, Avient Corporation. Avient makes no representations, guarantees, or warranties of any kind with respect to the information contained in this document about its accuracy, suitability for particular applications, or the results obtained or obtainable using the information. Some of the information arises from laboratory work with small-scale equipment which may not provide a reliable indication of performance or properties obtained or obtainable on larger-scale equipment. Values reported as “typical” or stated without a range do not state minimum or maximum properties; consult your sales representative for property ranges and min/max specifications. Processing conditions can cause material properties to shift from the values stated in the information. Avient makes no warranties or guarantees respecting suitability of either Avient’s products or the information for your process or end-use application. You have the responsibility to conduct full-scale end-product performance testing to determine suitability in your application, and you assume all risk and liability arising from your use of the information and/or use or handling of any product. AVIENT MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, either with respect to the information or products reflected by the information. This literature shall NOT operate as permission, recommendation, or inducement to practice any patented invention without permission of the patent owner.